

12 GOLDEN HSE RULES



Work with a valid Work Permit when required



INCO-Drilling Personnel must NOT perform any gas tests



Verify isolation before work begins and use the specified life protecting equipment



INCO-Drilling Personnel must NOT perform any work in confined spaces



Obtain authorization before overriding or disabling safety critical equipment



INCO-Drilling Personnel must NOT perform any work at heights



Do not walk under a suspended load



Do not smoke outside designated smoking areas



No alcohol or drugs while working or driving



While driving, do not use your phone and do not exceed speed limits



Wear your seat belt



Follow prescribed Journey Management Plan

The Company, its employees, its consultants, agents and any persons acting on its behalf must abide, encourage and comply with these rules.